



Variante 1: Strom-Transmitter (gesteuerter Widerstand)
 First alternative: current transmitter (driven resistor)

Variante 2: Strom- oder Spannungsquelle
 Second alternative: current or voltage source

Sensorspeisung muss galvanisch getrennt sein!
 A galvanic isolation of the sensor power supply is required!

Note: Content is for general information only and is subject to change without notification.

THIS DRAWING IS CONFIDENTIAL AND COPYRIGHT PROPERTY OF THE MANUFACTURER AND MUST NOT BE COPIED OR LENT WITHOUT PERMISSION

Customer: Project: PO# Reference: Date:	Drawing: ColorPlus-AS REV: 01
	Title: ColorPlus Terminal box Connecting diagram
	DATE: 02/10/08 DWG BY: PRDCM



ProDetec Pty.Ltd.
 P. +61 (02) 9620 8700
 F. +61 (02) 9620 8755
 E. info@prodetec.com.au
 A. 17/38 Powers Rd,
 Seven Hills NSW 2147
 www.prodetec.com.au